



## architect's field report

**Issue Date:** 10-04-19

**Site Visit Date:** 10-02-19

---

**Project Name:** MVHS Additions

**Project Number:** 18318

---

**Time:** 10:30 AM

**Site Conditions:** Good

---

**Attendees:** Larry Bishop – MPS

**Distribution:** (if different from above)

Donnie Love – MPS

Laura Slagel – MPS

Paulette Myers - MPS

Kevin Chipman – ACPSD

Beth Clark – ACPSD

Dr. Shawn Foster – ACPSD

Jeffrey Reynolds – HGR

Mike Doyle - HGR

Carl White – MVHS

Brian Melson – BGA

Chris Morse – BGA

Kelley Rios – BGA

Mahyar Angooraj – BGA

Mark Watts – BGA

Michael Sexton – BGA

Ed Weaver – BGA

Robbie Roberson - ACPSD

---

**Writer:** Larry Bishop - MPS

"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."

Refer to AIA 201.4.2.2.

127 dunbar street, spartanburg, sc 29306  
o. 864 585 5678 f. 864 542 9451

mcmillanpazdansmith.com

## architect's field report

*The following notes represent our understanding of matters discussed and actions agreed upon. Please report corrections and/or omissions to the writer within five (5) working days.*

### **Observations:**

1. Attended bi-weekly OAC meeting.
2. Schedule update:
  - Started block.
  - Start rough in. Verify above counter receptacle rough in height.
  - Footings are ongoing in Area A.
3. Discussed kitchen toilet. Larry will check on floor covering.
4. Consider eliminating water coolers in the gym. They are provided in the corridor and Jeffrey will contact BGA.
5. The grease trap location is driven by the existing SD.
6. The unit below to the right of the loading dock will have to move most likely to the roof. Contractors to coordinate with school and Kevin to minimize downtime.



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."  
Refer to AIA 201.4.2.2.

## architect's field report

### Site Pictures:



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."  
Refer to AIA 201.4.2.2.

## architect's field report



### **End of Report**

"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."  
Refer to AIA 201.4.2.2.