



## architect's field report

**Issue Date:** 10-14-19

**Site Visit Date:** 10-09-19

---

**Project Name:** MVHS Additions

**Project Number:** 18318

---

**Time:** 10:00 AM

**Site Conditions:** Good

---

**Attendees:** Larry Bishop – MPS

**Distribution:** (if different from above)

Donnie Love – MPS

Laura Slagel – MPS

Paulette Myers - MPS

Kevin Chipman – ACPSD

Beth Clark – ACPSD

Dr. Shawn Foster – ACPSD

Jeffrey Reynolds – HGR

Mike Doyle - HGR

Carl White – MVHS

Brian Melson – BGA

Chris Morse – BGA

Kelley Rios – BGA

Mahyar Angooraj – BGA

Mark Watts – BGA

Michael Sexton – BGA

Ed Weaver – BGA

Robbie Roberson - ACPSD

---

**Writer:** Larry Bishop - MPS

"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."

Refer to AIA 201.4.2.2.

## architect's field report

*The following notes represent our understanding of matters discussed and actions agreed upon. Please report corrections and/or omissions to the writer within five (5) working days.*

### **Observations:**

1. Site visit.
2. Schedule update:
  - Masonry continues Area C.
  - Rough in continues area C.
  - Footings are ongoing in Area A.
  - Continuing demo Area A.
  - Site work continues.
3. Small HVAC unit near loading dock moved to roof.



4. Added bond beam at existing locker room Area A/B. Send info to Larry King.



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."  
Refer to AIA 201.4.2.2.

## architect's field report

### Site Pictures:



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."  
Refer to AIA 201.4.2.2.

## architect's field report



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."  
Refer to AIA 201.4.2.2.

## architect's field report



### **End of Report**

"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."  
Refer to AIA 201.4.2.2.