

architect's field report

Issue Date: 6-05-2020

Site Visit Date: 6-03-2020

Project Name: MVHS Additions

Project Number: 18318

Time: 8:00 AM

Site Conditions: Clear

Attendees: Larry Bishop – MPS

Distribution: (if different from above)

Donnie Love – MPS
Laura Slagel – MPS
Paulette Myers – MPS
Lauren Smith – MPS
Kevin Chipman – ACPSD
Beth Clark – ACPSD
Dr. Shawn Foster – ACPSD
Jeffrey Reynolds – HGR
Mike Doyle - HGR
Carl White – MVHS
Brian Melson – BGA
Chris Morse – BGA
Kelley Rios – BGA
Mahyar Angooraj – BGA
Mark Watts – BGA
Michael Sexton – BGA
Ed Weaver – BGA
Robbie Roberson - ACPSD

Writer: Larry Bishop - MPS

"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.

architect's field report

The following notes represent our understanding of matters discussed and actions agreed upon. Please report corrections and/or omissions to the writer within five (5) working days.

Observations:

1. Weekly site visit, attended Pre-OSF Overhead Inspection with third party inspector and attended contractor meeting.
2. No delivery issues noted due to Covid-19.
3. HGR continues to stress social distancing to personnel and to stay home if sick.
4. OSF overhead inspection Areas A and B on Friday, June 5, 2020. The Pre-OSF Overhead overall was good. Except for some low voltage items the discrepancies found would be clear by inspection time.
5. The mechanical engineer confirmed by phone zip ties to connect flexible duct to hard duct for exhaust fans is acceptable if the zip ties are UL listed and above ACT:



6. Area A/B Progress:
 - MEP continues
 - Finalizing glass and doors.
 - Working on finishes.
 - Installing below ceiling devices.

"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1." Refer to AIA 201.4.2.2.

architect's field report

- Installing metal panels:



7. Area C Progress:
 - MEP continues.
 - Painting continues.
 - Working on overhead inspection items first floor and second floor.
8. Site work continues: Fine grading and sidewalks:



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."

Refer to AIA 201.4.2.2.

architect's field report



9. Next OAC June 10, 2020 at 10:30 AM.

"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."

Refer to AIA 201.4.2.2.

architect's field report

Pictures Area A and B



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1." Refer to AIA 201.4.2.2.

architect's field report




Pictures Area C:



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.

architect's field report



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.

127 dunbar street, spartanburg, sc 29306
o. 864 585 5678 f. 864 542 9451

mcmillanpazdansmith.com

architect's field report



End of Report

"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.