

architect's field report

Issue Date: 6-18-2020

Site Visit Date: 6-17-2020

Project Name: MVHS Additions

Project Number: 18318

Time: 9:30 AM

Site Conditions: Clear

Attendees: Larry Bishop – MPS

Distribution: (if different from above)

Donnie Love – MPS

Laura Slagel – MPS

Paulette Myers – MPS

Lauren Smith – MPS

Kevin Chipman – ACPSD

Beth Clark – ACPSD

Dr. Shawn Foster – ACPSD

Jeffrey Reynolds – HGR

Mike Doyle - HGR

Carl White – MVHS

Brian Melson – BGA

Chris Morse – BGA

Kelley Rios – BGA

Mahyar Angooraj – BGA

Mark Watts – BGA

Michael Sexton – BGA

Ed Weaver – BGA

Robbie Roberson – ACPSD

Blake Tillman - BGA

Writer: Larry Bishop - MPS

"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.



architect's field report

The following notes represent our understanding of matters discussed and actions agreed upon. Please report corrections and/or omissions to the writer within five (5) working days.

Observations:

1. Weekly site visit and attended contractor meeting.
2. No delivery issues noted due to Covid-19.
3. HGR continues to stress social distancing to personnel and to stay home if sick.
4. HGR continues to work on OSF overhead inspection Areas A and B discrepancies.
5. Area A/B Progress:
 - MEP continues
 - Finalizing glass and doors.
 - Working on finishes.
 - Installing below ceiling devices.
 - Installing floor covering.
 - Installing gym floor.
6. Area C Progress:
 - MEP continues.
 - Painting continues.
 - Preparing for overhead inspection first floor and second floor.
 - Start HVAC units.

"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1." Refer to AIA 201.4.2.2.

architect's field report

7. Site work continues: Fine grading and sidewalks. Pond needs some attention especially bare spots, reference recent SWPPP reports.



8. Metal panel installation completed. MPS concerned about seams at corners rather than wrap. HGR has contacted the supplier and installer:



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1." Refer to AIA 201.4.2.2.

architect's field report

9. MPS reviewing the need for an access panel in the hard ceiling Vestibule V514;



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."

Refer to AIA 201.4.2.2.


architect's field report

10. Sprinklers above duct in storage room S511 remain and sprinklers added below:



11. Record copies of tray product info is required for files.

12. Sprinklers near joists in gym under review:





13. Next OAC meeting TBD.

"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."

Refer to AIA 201.4.2.2.

architect's field report

Pictures Area A and B



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1." Refer to AIA 201.4.2.2.

architect's field report



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1." Refer to AIA 201.4.2.2.

127 dunbar street, spartanburg, sc 29306
o. 864 585 5678 f. 864 542 9451

mcmillanpazdansmith.com

architect's field report





Pictures Area C:



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.

architect's field report



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1." Refer to AIA 201.4.2.2.

127 dunbar street, spartanburg, sc 29306
o. 864 585 5678 f. 864 542 9451

mcmillanpazdansmith.com

architect's field report



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1." Refer to AIA 201.4.2.2.

architect's field report



End of Report

"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.

127 dunbar street, spartanburg, sc 29306
o. 864 585 5678 f. 864 542 9451

mcmillanpazdansmith.com