



architect's field report

Issue Date: 11-11-19

Site Visit Date: 11-06-19

Project Name: MVHS Additions

Project Number: 18318

Time: 10:15 AM

Site Conditions: Good

Attendees: Larry Bishop – MPS

Distribution: (if different from above)

Donnie Love – MPS
Laura Slagel – MPS
Paulette Myers - MPS
Kevin Chipman – ACPSD
Beth Clark – ACPSD
Dr. Shawn Foster – ACPSD
Jeffrey Reynolds – HGR
Mike Doyle - HGR
Carl White – MVHS
Brian Melson – BGA
Chris Morse – BGA
Kelley Rios – BGA
Mahyar Angooraj – BGA
Mark Watts – BGA
Michael Sexton – BGA
Ed Weaver – BGA
Robbie Roberson - ACPSD

Writer: Larry Bishop - MPS

"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.

127 dunbar street, spartanburg, sc 29306
o. 864 585 5678 f. 864 542 9451

mcmillanpazdansmith.com



architect's field report

The following notes represent our understanding of matters discussed and actions agreed upon. Please report corrections and/or omissions to the writer within five (5) working days.

Observations:

1. Site visit.
2. Progress Area A:
 - The following are prepped for slab:
 - Classroom 508
 - Classroom 509
 - STO S518
 - Toilets
 - Electrical 5A
 - IT 5B
 - Corridor C515
 - The following slabs are in place:
 - Auxiliary Gym 510. Masonry walls started.
 - Multipurpose 513
 - STO 511
3. Progress Area B:
 - Masonry continues foundations.
 - Under slab continues.
 - Compacting area
4. Progress Area C:
 - Masonry continues level 1.
 - Steel ready to install for level 2 floor.
 - Rough in continues.

"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.

architect's field report

Site Pictures:



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.

architect's field report



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.

architect's field report



End of Report

"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.