

architect's field report

Issue Date: 3-30-2020

Site Visit Date: 3-25-2020

Project Name: MVHS Additions

Project Number: 18318

Time: 10:00 AM

Site Conditions: Wet from overnight rain

Attendees: Larry Bishop – MPS

Distribution: (if different from above)

Donnie Love – MPS
Laura Slagel – MPS
Paulette Myers – MPS
Lauren Smith – MPS
Kevin Chipman – ACPSD
Beth Clark – ACPSD
Dr. Shawn Foster – ACPSD
Jeffrey Reynolds – HGR
Mike Doyle - HGR
Carl White – MVHS
Brian Melson – BGA
Chris Morse – BGA
Kelley Rios – BGA
Mahyar Angooraj – BGA
Mark Watts – BGA
Michael Sexton – BGA
Ed Weaver – BGA
Robbie Roberson - ACPSD

Writer: Larry Bishop, MPS

"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.

architect's field report

The following notes represent our understanding of matters discussed and actions agreed upon. Please report corrections and/or omissions to the writer within five (5) working days.

Observations:


1. Site visit.
2. Roof:
 - Roof work continues on Area A/B
 - Start roof Area C when deck is complete.
3. Area A/B:
 - MEP continues.
 - Ceiling grid continues.
 - Interior framing continues.
 - Storefront continues.
4. Area C:
 - Power company working on transformer
 - MEP continues.
 - Completing roof deck.
 - Brick veneer continues.
5. Hand wash sinks at each portable toilet area. Good job.



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.


architect's field report

Pictures Area A and B:



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.

architect's field report



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.

architect's field report



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.

127 dunbar street, spartanburg, sc 29306
o. 864 585 5678 f. 864 542 9451

mcmillanpazdansmith.com

architect's field report



Pictures Area C:



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.

architect's field report



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.

127 dunbar street, spartanburg, sc 29306
o. 864 585 5678 f. 864 542 9451


mcmillanpazdansmith.com

architect's field report



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.

architect's field report



"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.

architect's field report



End of Report

"The Architect will neither have control over or charge of, nor be responsible for, the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents, except as provided in Subparagraph 3.3-1."
Refer to AIA 201.4.2.2.